

Facility Inspected	☐ Chesterfield Landfill	☐ Clover Landfill	☐ Mt. Storm Phase A Landfill
	☑ VCHEC Landfill	☐ Yorktown Landfill	☐ Mt. Storm Phase B Landfill
Date of Inspection	September 17, 2024	Inspected By:	James F. Shields
Professional Engineer	James F. Shields	Virginia PE Registration Number	0402055777

Professional Engineer Certification Statement

I certify that the inspection of the above listed CCR Landfill was conducted in conformance with the requirements listed in 40 CFR Section 257.84, *Inspection Requirements for CCR Landfills*, and with generally accepted good engineering practices. This Certification/Statement of Professional Opinion is limited to the information available to GAI Consultants at the time the site visit was performed. The use of the words "certification" and/or "certify" in this document shall be interpreted and construed as a Statement of Professional Opinion and is not and shall not be interpreted or construed as a guarantee, warranty, or legal opinion.

Print Name:	James F. Shields	Title:	Engineering Manager
Signature:	Jum Slim	Date:	1/2/2025

Place Stamp Here

JAMES FARROW SHIELDS
Lic. No. 0402055777

<u>Inspection Results – VCHEC Landfill</u>

		Yes	No				
Was a review performed of available information regarding the status and condition of the CCR unit, including files in the operating record?							
		Yes	No				
Was a visual inspection performed to identify signs malfunction of the CCR unit?	☒						
Identify any changes in the geometry of the unit sind inspection.	e the previous ann	ual					
No changes were made in the geometry of the unit since the previous inspection. CCR placement continues in accordance with the Station's approved plans and specifications.							
Present volume of the CCR contained in the unit at the time of the inspection (cubic yards) 9,029,000							
Identify any appearances of an actual or potential st unit or existing conditions that are disrupting or have operation and safety of the CCR unit.							
None observed.							
Identify any changes that may have affected the state since the previous annual inspection.	bility or operation o	of the u	ınit				
None observed.							
Additional comments							
No additional comments.							

© 2024 GAI CONSULTANTS gaiconsultants.com